

**A Bird's view over:
Central Neighborhood near Horton
Ave and 7th Street, Rainelle**



Pre-Disaster Aerial View

Imagery of September 2013




Image courtesy of Google Earth Pro

Removed Structure

Imagery of September 2013



Building REMOVED (Vacant Parcel)



Image courtesy of Google Earth Pro

Deed-Restricted Buyout Parcels

Imagery of September 2013



ACQUISITION or Buyout Property



Image courtesy of Google Earth Pro

Imagery of September 2013

Mitigated Structures by Elevating to Design Flood Elevation (DFE)






Mitigation RECONSTRUCTION



Image courtesy of Google Earth Pro

Imagery of October 2020



-  Building REMOVED (Vacant Parcel)
-  ACQUISITION or Buyout Property
-  Mitigation RECONSTRUCTION