A Bird's view over: Central Neighborhood near Horton Ave and 7th Street, Rainelle

w

Chan

North



Pre-Disaster Aerial View

Imagery of September 2013



Image courtesy of Google Earth Pro

Removed Structure

Imagery of September 2013



Image courtesy of Google Earth Pro

Deed-Restricted Buyout Parcels

Imagery of September 2013



Image courtesy of Google Earth Pro

Imagery of September 2013

Mitigation RECONSTRUCTION


1

Mitigated Structures by Elevating to Design Flood Elevation (DFE)



Image courtesy of Google Earth Pro

Imagery of October 2020





Building REMOVED (Vacant Parcel) ACQUISITION or Buyout Property Mitigation RECONSTRUCTION