

A Bird's view over:
Howard Creek Neighborhood
near Big Draft Road and Garden
Street, White Sulphur Springs





Pre-Disaster Aerial View

Imagery of June 2016




Image courtesy of Google Earth Pro



Removed Structures

Imagery of June 2016



 Building REMOVED (Vacant Parcel)


Google earth


Image courtesy of Google Earth Pro & Google Street View



Deed-Restricted Buyout Parcels

Imagery of October 2019



 ACQUISITION or Buyout Property


Google earth

Image courtesy of Google Earth Pro & Google Street View



Non-Mitigated Repaired Structures

Imagery of October 2019



Google earth


Image courtesy of Google Earth Pro & Google Street View



Mitigated Structures, Elevated to Design Flood Elevation (DFE)

Imagery of October 2019




 Mitigation
RECONSTRUCTION





Google earth
Image courtesy of Google Earth
Pro & Google Street View



Mitigated & Non-Mitigated Properties

Imagery of October 2019




-  Building REMOVED (Vacant Parcel)
-  ACQUISITION or Buyout Property
-  REPAIRED or Substantially Damaged (>50%)
-  Mitigation RECONSTRUCTION

Google earth

Image courtesy of Google Earth Pro

A Bird's view over:
**Freeland Ave, Eastern Main
Street, and Wades Creek,
White Sulphur Springs**





Pre-Disaster Aerial View

Imagery of June 2016






Removed Structures

Imagery of June 2016



 Building REMOVED (Vacant Parcel)

Google earth


Image courtesy of Google Earth Pro



Mitigated Structures by Elevating to Design Flood Elevation (DFE)

Imagery of June 2016



 Mitigation RECONSTRUCTION

Google earth



Image courtesy of Google Earth Pro



Imagery of October 2019



Google earth
Image courtesy of Google Earth Pro

	Building REMOVED (Vacant Parcel)
	Mitigation RECONSTRUCTION