

A Bird's view over:

Howard Creek Neighborhood near Big Draft Road and Garden Street, White Sulphur Springs



Pre-Disaster Aerial View

Imagery of June 2016




Image courtesy of Google Earth Pro

Removed Structures

Imagery of June 2016





 Building REMOVED (Vacant Parcel)

Google earth
Image courtesy of Google Earth Pro
& Google Street View

Deed-Restricted Buyout Parcels

Imagery of October 2019




 ACQUISITION or Buyout Property


Google earth

Image courtesy of Google Earth Pro
& Google Street View

Non-Mitigated Repaired Structures

Imagery of October 2019



 REPAIRED of Substantially Damaged (>50%) Building

Google earth

Image courtesy of Google Earth Pro
& Google Street View

Mitigated Structures, Elevated to Design Flood Elevation (DFE)

Imagery of October 2019








 Mitigation RECONSTRUCTION

Google earth
Image courtesy of Google Earth Pro
& Google Street View

Mitigated & Non-Mitigated Properties

Imagery of October 2019



-  Building REMOVED (Vacant Parcel)
-  ACQUISITION or Buyout Property
-  REPAIRED or Substantially Damaged (>50%) Building
-  Mitigation RECONSTRUCTION