

**A Bird's view over:
Central Neighborhood near Horton
Ave and 7th Street, Rainelle**





Pre-Disaster Aerial View

Imagery of September 2013



Image courtesy of Google Earth Pro



Removed Structure

Imagery of September 2013



Building REMOVED (Vacant Parcel)



Image courtesy of Google Earth Pro



Deed-Restricted Buyout Parcels

Imagery of September 2013



ACQUISITION or Buyout Property



Image courtesy of Google Earth Pro



Mitigated Structures by Elevating to Design Flood Elevation (DFE)

Imagery of September 2013



Mitigation RECONSTRUCTION






Image courtesy of Google Earth Pro



Imagery of October 2020



-  Building REMOVED (Vacant Parcel)
-  ACQUISITION or Buyout Property
-  Mitigation RECONSTRUCTION




Image courtesy of Google Earth Pro