

A Bird's view over:
Howard Creek Neighborhood
near Big Draft Road and Garden
Street, White Sulphur Springs





Pre-Disaster Aerial View

Imagery of June 2016





Image courtesy of Google Earth Pro



Removed Structures

Imagery of June 2016



 Building REMOVED (Vacant Parcel)


Google earth
Image courtesy of Google Earth Pro
& Google Street View



Deed-Restricted Buyout Parcels

Imagery of October 2019




 ACQUISITION or Buyout Property


Google earth
Image courtesy of Google Earth Pro
& Google Street View



Non-Mitigated Repaired Structures

Imagery of October 2019



 REPAIRED of Substantially Damaged (>50%) Building

Google earth

Image courtesy of Google Earth Pro & Google Street View



Mitigated Structures, Elevated to Design Flood Elevation (DFE)

Imagery of October 2019



 Mitigation RECONSTRUCTION

Google earth





Image courtesy of Google Earth Pro
& Google Street View



Mitigated & Non-Mitigated Properties

Imagery of October 2019



-  Building REMOVED (Vacant Parcel)
-  ACQUISITION or Buyout Property
-  REPAIRED or Substantially Damaged (>50%) Building
-  Mitigation RECONSTRUCTION